

Ufs

No 1084

September 10, 2025

Notices to Mariners, SWEDEN



NtM-Editorial office
Swedish Maritime Administration
601 78 Norrköping
Sweden
Phone: +46 771 630 605
E-mail: ufs@sjofartsverket.se

Publisher: Patrik Wiberg
www.sjofartsverket.se



**SWEDISH MARITIME
ADMINISTRATION**

Affected charts and Notices

Each PDF-file consists of a number of notices also accessible on www.sjofartsverket.se/ntm

Each booklet contains information on changes made to official Swedish nautical charts, as well as essential information on occurrences that pertain to safe navigation in Swedish waters.

Information available on foreign waters is limited. Ufs is not suitable for the task of keeping BA-charts and other nautical charts updated.

Note: Unintentional page breaks may occur as the PDF-file is generated automatically.

Announcements – General information, e.g. new chart editions, statutes/decrees from national authorities

Notices – Chart corrections and temporary/preliminary notices for a given geographical location

An asterisk (*) in front of the notice number denotes that the notice is based on source material obtained from a Swedish national source and that the details stated therein affect Swedish waters.

When a notice number is followed by a '(P)' this signifies that the information contained therein is of a preliminary nature. An upcoming notice containing a chart correction will replace the former.

Similarly, when the letter 'T' is used this indicates that the notice is of a temporary nature.

In case no period of validity is stated, such a notice will be invalidated either when a new temporary notice or a chart correction replaces it.

Information in temporary and preliminary notices are generally available as an update to ENC. In case ENC updates are not available, the notice will state 'Not shown in ENC'.

Bearings are true and given clockwise from 000° to 360° and, when describing a light house beam, indicate a direction from seaward towards shore.

Note: Chartlets are intended to simplify chart correction work and are not always true to scale. Generally, these pictorials show the largest charted scale available for respective area.

The respective informant is responsible for factual content.

Please refer to more information on the use of Ufs in the official Swedish publication **Ufs A**.

Reporting dangers and errors

All observations concerning floating aids to navigation, unlit beacons and lights, objects adrift or any other occurrence that may have a detrimental impact on the safety at sea are to be reported to Sweden Traffic at the earliest possible opportunity.

Call: Sweden Traffic

Channel: Appropriate working channel

Phone: +46 771 630 685 (24/7)

E-mail: swedentraffic@sjofartsverket.se

[illegible]

ANNOUNCEMENTS

No Announcements in this booklet.

NOTICES

Areas without notices in this booklet

Bay of Bothnia
The Quark
Sea of Bothnia
Sea of Åland and Archipelago Sea
Gulf of Finland
Gulf of Riga
Northern Baltic
South-Eastern Baltic
South-Western Baltic
The Sound
The Belts
Kattegat
not area bound

Lake Mälaren and Södertälje Canal

* 19529

Chart: 111

Sweden. Lake Mälaren and Södertälje Canal. Mälaren. Björkfjärden. Grönsöfjärden. Arnöfjärden. Buoyage.

Amend	port-hand light spar buoy FI R 3s to	port-hand spar buoy	a)	59-19,391N	017-31,503E
Amend	east cardinal light spar buoy with topmark Q(3) 10s to	east cardinal light buoy Q(3) 10s	b)	59-17,897N	017-33,356E
Amend	light 'Långhällsudde' FI WRG 4s to	light 'Långhällsudde' FI WRG 3s	c)	59-17,047N	017-36,394E
Replace	beacon 'Tegelgrund' with radar reflector with	light 'Tegelgrund' with radar reflector FI R 3s	d)	59-26,253N	017-20,306E
Amend	light 'Ekskär' Q R to	light 'Ekskär' FI R 3s	e)	59-25,955N	017-22,864E
Delete	floodlight on beacon 'Tribergsudd'		f)	59-30,885N	017-10,331E

Adm. LoL vol. C 6680-6
Bsp Mälaren - Hjälmarén 2024/s23, s24, s25, s28

* 19531

Chart: 113, 1131, 1133

Sweden. Lake Mälaren and Södertälje Canal. Mälaren. Märsön. Ridöfjärden.
Galten. Buoyage.

Amend	starboard-hand light spar buoy Q G to	starboard-hand light spar buoy FI G 3s	a)	59-31,264N	016-59,131E
Amend	starboard-hand light spar buoy Q G to	starboard-hand light spar buoy FI G 3s	b)	59-30,934N	016-44,021E
Amend	port-hand light spar buoy Q R to	port-hand light spar buoy FI R 3s	c)	59-30,878N	016-43,700E
Amend	port-hand light buoy Q R to	port-hand light buoy FI R 3s	d)	59-32,233N	016-35,028E
Amend	floodlit light 'Brobygrund' Q WRG to	floodlit light 'Brobygrund' FI(2) WRG 3s	e)	59-26,864N	016-15,030E
Amend	starboard-hand light buoy 'Västra Tallklubben N' Q G to	starboard-hand light buoy 'Västra Tallklubben N' FI G 3s	f)	59-27,723N	016-12,423E
Amend	port-hand light buoy Q R to	port-hand light buoy FI R 3s	g)	59-27,636N	016-12,235E
Amend	port-hand light buoy Q R to	port-hand light buoy FI R 3s	h)	59-27,410N	016-10,499E
Amend	port-hand light buoy Q R to	port-hand light buoy FI R 3s	i)	59-27,689N	016-11,462E
Amend	starboard-hand light buoy Q G to	starboard-hand light buoy FI G 3s	j)	59-27,739N	016-11,385E
Amend	starboard-hand light buoy Q G to	starboard-hand light buoy FI G 3s	k)	59-27,858N	016-11,747E
Amend	floodlit light 'Skylgrund' FI(3) WRG 9s to	floodlit light 'Skylgrund' FI(2) WRG 3s	l)	59-27,663N	016-11,461E

Adm. LoL vol. C 6692-8
Adm. LoL vol. C 6694-6
Bsp Mälaren - Hjälmarén 2024/s18, s19, s21, s22, s23, s61, s62, s63

Sjöfartsverket. Publ. 10 Sep 2025

* 19550

Chart: 113

Sweden. Lake Mälaren and Södertälje Canal. Mälaren. Blacken. N of Torshälla.
Fläskåsen. Buoyage.

Insert	east cardinal spar buoy with top mark	59-28,113N	016-28,670E
--------	---------------------------------------	------------	-------------

Bsp Mälaren - Hjälmarén 2024/s20

Sjöfartsverket. Publ. 10 Sep 2025

Central Baltic

*** 19417**

Chart: 6231

Sweden. Central Baltic. SSE of Västervik. Hornsviken. Hornsudde. Beacons.

Delete	beacon	a)	57-41,788N	016-43,813E
Delete	beacon	b)	57-41,781N	016-43,929E

Bsp Kalmarsund 2023/s31, Bsp Ostkusten 2023/s55, Bsp Ostkusten 2025/s55

Transportstyrelsen. Publ. 05 Sep 2025

Southern Baltic


* 19472

Chart: 839

Sweden. Southern Baltic. Trelleborg. Trelleborgs hamn. Radar reflector.

Amend	floodlit tower	floodlit tower with radar reflector	55-21,411N	013-08,950E
-------	----------------	-------------------------------------	------------	-------------

Bsp Sydkusten 2020/s53, BSP Sydkusten 2025/s53



Radar Reflector

Transportstyrelsen. Publ. 10 Sep 2025

*** 19524 (T)****Chart: 742****Sweden. Southern Baltic. S of Karlshamn. Hanö. Work on light. Affected light range and sector.**


Time: September 15 - November 20, 2025.

The all-round light on the island of 'Hanö' is being renovated. During the work, the range will be reduced to 12 M and the sector will be limited to shining in a southeasterly direction.

light 'Hanö' Fl(3) 12s	56-00,82N	014-50,77E
------------------------	-----------	------------

Adm. LoL. C7538

Bsp Hanöbukten 2022/s06, s20, s23



Sjöfartsverket. Publ. 08 Sep 2025

Skagerrak

* 19406

Chart: 932

Sweden. Skagerrak. Orust. W of Mollösund. Söskär. Wreck.

Insert	wreck, least depth unknown	58-04,34N	011-25,86E
--------	----------------------------	-----------	------------

BSP Västkusten N 2025/s23, Bsp Västkusten S 2025/s11

Kustbevakningen. Publ. 10 Sep 2025

* 19463

Chart: 937

Sweden. Skagerrak. NW of Strömstad. Långörännan. Tångarna. Underwater rock.

Insert	underwater rock	58-57,667N	011-07,083E
--------	-----------------	------------	-------------

BSP Västkusten N 2025/s06, s09



New underwater rock in 'Långörännan'

Sjöfartsverket. Publ. 09 Sep 2025

Lake Vänern and Trollhätte Canal

*** 19467****Chart: 1331**

Sweden. Lake Vänern and Trollhätte Canal. Vänern. Kållandsö. Stor-Eken. Spikefjorden. Buoyage.

Insert	special purpose spar buoy with topmark	58-41,890N	013-12,595E
--------	--	------------	-------------

Bsp Vänern 2022/s43

Transportstyrelsen. Publ. 10 Sep 2025

Inshore waters

*** 19523 (T)****Chart: 121**

Sweden. Inshore waters. Vättern. Karlsborg. Vanäs udde. Light 'Vanäs'. Unreliable sectors.

Time: Until November 2, 2025.

During the time stated above, renovation work is underway at the light 'Vanäs'. The sectors are to be considered as unreliable during this period.

Vanäs Fl(3) WRG 9s 9,8M	58-32,293N	014-32,406E
-------------------------	------------	-------------

Bsp Göta Kanal 2022/s09, s10, s16, s24

Sjöfartsverket. Publ. 05 Sep 2025

*** 19538 (T)****Chart: 121**

Sweden. Inshore waters. Motala. Motalaviken. Light 'Hundsten'. Unlit.

Time: Estimated until 19 October, 2025.

The Light is temporarily unlit due to severed power cable.

Light 'Hundsten' Fl WRG 3s	58-31,755N	015-00,770E
----------------------------	------------	-------------

Bsp Göta Kanal 2022/s08, s09, s11, s23

AB Göta kanalbolag. Publ. 09 Sep 2025